



FAST FORWARD



The 12041-2400-0X is the industry's standard bad b2 (d bt)9(1)7e (2(d b44.5 (y)-3 f

Altitude: Rapid Decompression

MIL-STD-810G, Test Method 500.5, Procedure III

Chemical Resistance

MIL-STD-810G, Test Method 504.1, Procedure I

Solar Radiation

MIL-STD-810G, Test Method 505.5, Procedure I, Climate Category A1

Rain

MIL-STD-810G, Test Method 506.5, Procedure I

Fungus

MIL-STD-810G, Test Method 508.6

Salt-Fog

MIL-STD-810G, Test Method 509.5

Loose Cargo

MIL-STD-810G, Test Method 514.6, Procedure II, Category 5

INTERFACES

AC Input

DC Input

Auxiliary

LED Indicators